

North Starr Inspections

15:32PM January 23, 2006

Photo Attachments



Damaged starter Shingles, back of house



Washer Vent not plumbed thru roof.



Light missing in laundry room



Missing cover on electrical junction box, Great Room



Install splash block right rear of house



Down spout not connected to Leader, north side of building.